

[illegible]

The figure shows three vertical columns, CL 1, CL 2, and CL 3, arranged horizontally. Each column has a total height of 22.7 cm. Two horizontal bars represent cracks in each column. The top crack is located at a distance of 19.4 cm from the base. The bottom crack locations are indicated by arrows pointing to specific heights: 2.27 cm for CL 1, 0.57 cm for CL 2, and 0.65 cm for CL 3.

